Weathertzation Assistance

Work Order Bid (ID)

WORK ORDER INFORMATION

Work Order Name: 13013SH2907Work Order Type: WeatherizationAudit Name: 13013SH2907

CLIENT INFORMATION

Client ID: 13013SH2907

AGENCY INFORMATION

Agency:Shelby County Community Services AgencyAgency Phone:(901) 222-4280Address:3772 South Hickory Ridge Mall, Suite 516Fax:(901) 222-4313

Memphis, TN 38115 Email Address:

Agency Contact: GAILLARD, GREG Work Phone:

Cell Phone: Email Address:

Company Name & License Number:	
Contractor's Signature:	

COMMENT

SITE BUILT 1957 AUDIT CONDUCTED 4/3/2012

Client ID: 13013SH2907

DOE Weatherization Assistant Version 8.6.0 Page 1 of 7

Measure 1 Infilt	ration Redctn			Componen	ts			Inspected
B/S A/C REPLAC SMALL), CAULK / GLAZE \	STORM WINDOW #1 WINDOW #2 CE BROKEN PANE WIN , WINDOW #9 (1 SMALL AND GLAZE WINDOWS WINDOW #6 TIC STAIRS	_)		LL) AND W	INDOW #	‡7 (3		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Su	Infiltration Reduction	Each	1					
2 Labor	Infiltration Reduction	Each	1					
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
Measure 2 Repl	ace A/C CE A/C WINDOW UNIT	COMPLE ⁻		Componen		£8		Inspected
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Cooling Equipmen	Window A/C -	Each	1					
2 Labor	Window A/C -	Each	1					
Other Detail								
			Measur	e Sub Total:			Sub Total:	
Field Notes:								

Measure 3 Us	er-Spec Ceiling R			Componen	ts ATT1			Inspected
Comment 756 SG								
RENA	IL ATTIC FACING			Estimated	,		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Attic Insulation - Blown Cellulose - R-19	SqFt	756					
2 Labor	Added Misc Cost - Blown Cellulose - R-19	Each	756					
Other Detail				1		1		
			Measur	re Sub Total:		,	Sub Total:	
	VH Pipe Insulation OWATER LINES HOT AND	O COLD		Componen Estimated			Actual	Inspected
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail						1		
			Measur	re Sub Total:		,	Sub Total:	
Field Notes:								

Measure 5 Wa	ı ll Insulation Q. FT. R-13			Componen	ts WL1,V	VL2,W	L3,WL4	Inspected
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	540.0					
2 Labor	Wall Insulation - Blown Cellulose - 2x4 Filled	SqFt	1					
Other Detail								
			Measure	e Sub Total:		;	Sub Total:	
Measure 6 Flo	o r Ins. R-19 Q. FT. R-19			Componen				Inspected
Comment 756 SC	Q. FT. R-19	Units		Estimated	1	Ofty	Actual	
Comment 756 SC		<i>Units</i> SqFt	Qty 756	•		Qty		Inspected
Comment 756 SC # Material / Labor 1 Insulation	Q. FT. R-19 Description / Comment Floor Insulation -		Qty	Estimated	1	Qty	Actual	
Comment 756 SC # Material / Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	SqFt	Qty 756	Estimated	1	Qty	Actual	
Comment 756 SC # Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	SqFt	Qty 756	Estimated	1	Qty	Actual	
Comment 756 SC # Material / Labor 1 Insulation 2 Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	SqFt	Qty 756	Estimated	1	Qty	Actual	
Comment 756 SC# Material / Labor1 Insulation2 Labor	Description / Comment Floor Insulation - Fiberglass Batts - R-19 Floor Insulation -	SqFt	Qty 756 756	Estimated	1		Actual	

	rigerator Rplcmnt CE REFRIGERATOR 18	CU. FT.		Componen	ts		ı	nspected
		331111		Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Refrigerators	REFRIGERATOR 18 CU. FT.	Each	1					
2 Labor	REFRIGERATOR 18 CU. FT.	Each	1					
Other Detail								
			Measur	e Sub Total:] ,	Sub Total:	
	Monitor is Needed L 2 CO MONITORS			Componen				Inspected
Comment INSTAL	L 2 CO MONITORS			Estimated			Actual	
Comment INSTAL # Material / Labor	L 2 CO MONITORS Description / Comment	Units	Qty	-		Qty		Inspected
Comment INSTAL	L 2 CO MONITORS Description / Comment	<i>Units</i> Each		Estimated		Qty	Actual	
Comment INSTAL# Material / Labor1 Health and Safety	L 2 CO MONITORS Description / Comment		Qty	Estimated		Qty	Actual	
Comment INSTAL# Material / Labor1 Health and Safety	L 2 CO MONITORS Description / Comment CO monitor	Each	Qty 2	Estimated		Qty	Actual	
Comment INSTAL# Material / Labor1 Health and Safety2 Labor	L 2 CO MONITORS Description / Comment CO monitor	Each	Qty 2	Estimated		Qty	Actual	
Comment INSTAL# Material / Labor1 Health and Safety2 Labor	L 2 CO MONITORS Description / Comment CO monitor	Each	Qty 2	Estimated		Qty	Actual	
Comment INSTAL# Material / Labor1 Health and Safety2 Labor	L 2 CO MONITORS Description / Comment CO monitor	Each	Qty 2 2	Estimated			Actual	

		Any Other Venting Relater er Heat)	ted Probl	em	Componen	ts		1	Inspected
C	Comment REVEN	WATER HEATER TO	OUTSIDE	12 FT					
					Estimated			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Equipment	Each	1					
2	Labor	Labor	Hour	1					
C	Other Detail								
Ļ									
] []		
				Measur	re Sub Total:		•	Sub Total:	
		Other Water Heating Pro			Componen				Inspected
C	Comment REPLAC	CE FLEXLINE FOR GAS	LINES	Qtv	Estimated		Qtv	Actual	
C		•		Qty 1	-		Qty		Inspected
# 1	Comment REPLAC	Description / Comment	LINES <i>Unit</i> s		Estimated		Qty	Actual	
C # 1	Comment REPLAC Material / Labor Health and Safety	Description / Comment Equipment	Units Each	1	Estimated		Qty	Actual	
C # 1	Comment REPLAC Material / Labor Health and Safety Labor	Description / Comment Equipment	Units Each	1	Estimated		Qty	Actual	
# 1	Comment REPLAC Material / Labor Health and Safety Labor	Description / Comment Equipment	Units Each Hour	1	Estimated			Actual	Total

-	Measure 11 Pres	sureRelief Piping Need	ded		Compone	nts			Inspected
C	omment								
					Estimate			Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Pressure relief piping	Each	1					
2	Labor	Labor	Each	1					
C	Other Detail								
				Measure	e Sub Total:] .	Sub Total:	
	Field Notes:								
ı	-	or Barrier Needed ement/Crawlspace)			Compone	nts			Inspected
C	omment 793 SQ								
	omment 700 0Q	' '			Estimate	d		Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Basement / crawlspace vapor barrier	SqFt	793					
2	Labor	Labor	Each	793					
0	Other Detail								
Ĭ	arci Detail								
Ī									
				Measure	e Sub Total:] ,	Sub Total:	
	Field Notes:								
			Work Or	der Grai	nd Total:		Gran	d Total:	